	(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER	
REF	FERENCES: ATTACHMENT TO L-1613 23 AUGUST 1966 PAGE 1	
	PETROLEUM PRODUCTS STORAGE UNDERGROUND DUONG NHAM, NORTH VIETNAM 2101N 10630E	
	(SEE NPIC BRIEFING BOARD L-1225 FOR COMPARISON)	
1	SIGNIFICANCE:	
	THIS BRIEFING BOARD DEPICTS BOMB DAMAGE RESULTING FROM AN AIR	
	STRIKE ON DUONG NHAM PETROLEUM PRODUCTS STORAGE.	
2.	LOCATION:	
	THE STORAGE AREA IS LOCATED 0.5 NM NORTH-NORTHEAST OF DUONG NHAM,	
	ADJACENT TO THE SONG KINH THAY (RIVER), AND SIXTEEN NM NORTHWEST OF	
	HAI PHONG.	
3.	MISSION READOUT:	
	PRE-STRIKE PHOTOGRAPHY REVEALS	2
	A POL STORAGE AREA CONTAINING FOUR POL TANKS UNDER CONSTRUCTION (EACH	
	WITH A U-SHAPED PROTECTION WALL), THREE PROBABLE POL TANK BASES UNDER	
	CONSTRUCTION, AND EIGHT STORAGE/SUPPORT BUILDINGS.	
	(NOT SHOWN ON GRAPHIC) STRIKE PHOTOGRAPHY	2
	REVEALS DENSE BLACK SMOKE RISING FROM THE ENTIRE TARGET,	
	BUT NO DAMAGE IS OBSERVED TO THE NUMEROUS POL DRUMS LOCATED ADJACENT	
	TO THE RIVER LANDING, NOR TO TWO MOTORIZED POL BARGES AT THE LANDING.	
	POST-STRIKE PHOTOGRAPHY OF REVEALS	2
	TWO POL TANKS DESTROYED, ONE TANK DAMAGED, AND ONE TANK INTACT AT THE	
	These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support	

NGA review(s) completed.

5X1

Approved For Release 2006/02/27 : CIA-RISED BOX 1000000000000008-7


25X1


1	REFERENCES: ATTACHMENT TO L-1613 23 AUGUST 1966 PAGE 2
	DUONG NHAM POL STORAGE AREA. THE THREE PROBABLE TANK BASES UNDER
1	CONSTRUCTION HAVE APPARENTLY NEVER BEEN COMPLETED. AT
	LEAST ONE HUNDRED AND THIRTY-SEVEN POL DRUMS IN OPEN STORAGE ARE
	LOCATED ADJACENT TO THE RIVER LANDING AND ALONG THE BASE OF A HILL
	IN A RAVINE. NONE OF THESE DRUMS ARE DAMAGED. A PIPELINE EXTENDING
	FROM THE RIVER TO THE POL TANKS MAY HAVE SUSTAINED DAMAGE.
ſ	

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Collateral Support Division, NPIC.

Approved For Release 2006/02/27 : CIA-RDP79-00849A000300060008-







(7-15-1030

REPRODUCTION OF THIS DOCUMENT IN WHOLE OR IN PART IS PROHIBITED EXCEPT WITH THE PHINGSION OF THE OFFICE OF ORIGIN.